



## CERTIFICATE


Name of Building: - **B.R.D School at Kulujhanda, P.O- Mandhala, Tehsil-Baddi, Distt- Solan (HP)**

It is certified that: - As per plan attached Drg. No. dated NIL

1. For structural adequacy, Structure design need to take soil bearing capacity seismic forces in to consideration and quality work i.e. water cement ratio, steel diameter, slab diameter, slab steel design, cantilever, column dia footing design etc. building should be inspected at the time of construction which cannot be ascertained at this stage.
2. The building has been inspected by the concerned Junior Engineer/ along with Assistant Engineer, Baddi Sub-Division, and HP.PWD Baddi on dated 10/10/2022. It has been found that the building seems safe for normal loading.
3. This certificate is valid for **five years i.e. 2022-2023 to 2026-2027** and this Certificate is not valid for any legal purpose.

  
Junior Engineer  
HP.PWD.Sub Division  
Barotiwala,

  
Assistant Engineer  
HPPWD. Sub division  
Baddi

  
Executive Engineer  
HPPWD Division  
Nalagarh