




CERTIFICATE

The Inspection of school building of Rose Public School Suliali in Tehsil Nurpur Distt Kangra (H.P) has been conducted by the Assistant Engineer on 03/04/2025 Sub Division, HPPWD., Suliali accompanied with Junior Engineer. On the basis of their inspection report, it has been found that no Earthquakes resistant norms have been adopted for the construction of School building. No structural drawing approved by the competent government agency were produced by the school authority. The structure of the building is a non Engineering structure. Hence, the structural safety of building can't be ensured specially from Earthquake point of view. This Department will not responsible for any type of loss of life and property etc., if this structure fails under any circumstances.

However, as per visual inspection, the building appears to be safe and accordingly, the Building Safety Certificate is being issued by this Department from 01.04.2025 to 31.03.2026. This Department could not assess the structural safety of said building as the same was not constructed under the supervision of this Department.


Junior Engineer,
Section Suliali


Assistant Engineer
Suliali Sub-Division, HPPWD.,
Suliali.

C/S

Executive Engineer
Nurpur Division HPPWD.,
Nurpur.