HIMACHAL PRADESH
PUBLIC WORKS DEPARTMENT

No.PWN/CB/WA/School Building/2025-26- 4896-97 Dated:- 21 -02-2026.

To

The Principal,
Rose Public School Suliali
Tehsil-Nurpur, Distt.-Kangra (H.P)

Subject: - Regarding School Building Safety Certificate.

Enclosed please find herewith School Building Safety Certificate for the financial year 2026-27 for favor of further necessary action please.

DA/Certificate.

Executive Engineer,
Nurpur Division, HPPWD,
Nurpur.

Copy to the Assistant Engineer, Sub-Division, Suliali HPPWD, for information w.r.t. his office letter No.551 dated 18.02.2026.

Executive Engineer,
Nurpur Division, HPPWD,
Nurpur.

Scanned with OKEN Scanner

CERTIFICATE

The Inspection of school building of Rose public School V.P.O. Suliali in Tehsil Nurpur Distt Kangra (H.P) has been conducted by the Assistant Engineer on 17.02.2026 Sub Division, HPPWD., Suliali accompanied with Junior Engineer. On the basis of their inspection report, it has been found that no Earthquakes resistant norms have been adopted for the construction of School building. No structural drawing approved by the competent government agency were produced by the school authority. The structure of the building is a non Engineering structure. Hence, the structural safety of building can't be ensured specially from Earthquake point of view. This Department will not responsible for any type of loss of life and property etc., if this structure fails under any circumstances.

However, as per visual inspection, the building appears to be safe and accordingly, the Building Safety Certificate is being issued by this Department from 01.04.2026 to 31.03.2027. This Department could not assess the structural safety of said building as the same was not constructed under the supervision of this Department.

Junior Engineer,
Section Suliali

Assistant Engineer
Suliali Sub-Division, HPPWD.,
Suliali.

Executive Engineer
Nurpur Division HPPWD.,
Nurpur. 21/02/2026

Scanned with OKEN Scanner